

TM



NATIONAL OILWELL VARCO

PRODUCT INFORMATION

Product Bulletin No.:01-23-15-PP

Rev 00

14-P-220 TORQUE PRO SYSTEM MANUAL REVISION

Date: 01/23/2015

Subject: 14-P-220 Torque Pro System Manual Revision

Product: 14-P-220 Torque Pro System

Affected

Assemblies: This bulletin applies to the manual for the 14-P-220 and affects the following assemblies: 80503104, 80503106, 80503107, 80503109, and 80503109S.

Objectives: Notify customers of a revision in the 14-P-220 Torque Pro System manual.

Issue: Provide customers with the latest revision to the 14-P-220 Torque Pro System manual.

Solution: Customers who utilize the 14-P-220 Torque Pro System should attain the latest copy of the manual, which is currently Revision I, from their local NOV service center

Or

By clicking on this link [80503209-MAN](#), to always download the latest revision to the manual.

Please contact your local National Oilwell Varco (NOV) Service Center if you have any questions regarding this product bulletin.

Operators should also refer to previous NOV Product Information Bulletins and Safety Alerts by signing in to the Product Bulletin Search, available below 'Application Groups' at <https://portal.mynov.com/> once logged in. For information on registering, please visit <https://www.nov.com/Search/register.aspx>.

Failure to follow the recommendations and/or guidance in NOV Manuals and Product Bulletins may result in death, bodily injury or property damage.